







HIETAKARI®



8/25 7MRLM

M16, M17, M18



Parts




1. 4x90 mm
x11




2. 6x35 mm
x11




3. 4.2x13 mm
x24



4. x2



5. x4



6. 4.2x16mm
x24




7. x4




8. x6




9. x10




10. x1




12. x1




13. x1




14. x1



11. x2




15. x1




16. x2 2


Parts




17. x2




18. 20x25 mm
x4



19. x1




20. x1




21. x12


Tools



A




B




C – Mounting foam
D – Silicone



E



Ø6 mm
Ø10 mm
F




G

1.


I.)

x2





II.)

x2




III.)


x2




2.




3.




I.)




II.)




4.






I.)




II.)




5.




6.




I.)





II.)





III.)




7.




8.




9.




10.




11.




12.




I.)




II.)






III.)




IV.)




13.




14.



15.



16.



17.

