





HIETAKARI®




8/25 77RLM


953



Parts



1. x1




2. x2

4/83 B7RLM




4/83 24RLM



4/83 14RLM




4/83 31RLM



4/83 B1RLM




4/83 B4RLM



4/83 B2RLM



4/83 28RLM



4/83 B5RLM +
4/83 B6RLM

6. x1


7. x1

8. x1


9. 3.5x25 mm
x1

10. x12


Tools




A




B
 $\varnothing 5 \text{ mm}$



C – Silicone




D




E







1



2




3




5


4



I a




II a




1

2




I b




II b


5




6




I




II




III



V



IV



8