





HIETAKARI®




8/25 6MRLM


S53




Parts




1. x1



2. x2




3. x3



4/83 31RLM




4/83 14RLM




6. x1




7. x1




8. x2



9. x1




10. x1




11. x1



12. x1




13. x1



14. x2

Tools



A

$\varnothing 4$ mm


$\varnothing 5$ mm

B


C – Silicone




E






F







G




1







2

 $\varnothing 4\text{ mm}$ 




5






3





4



5



6



12

