






HIE TAKARI®




616




Parts




1. x1




2. x1




3. A x2
B x0




4. A x2
B x0



5. A x2
B x4




6. A x2
B x4




7. 6x30 mm
x17



4/83 11RLM




9. x2




10. x2

8. 3.5x39 mm
x17




11. x8




12. x2




13. x2




14. x4




15. x4




16. x2



17. x2




18. x4



19. x2

Tools



A

$\varnothing 6\text{ mm}$
B


C – Silicone
D – Glue




E



F




G




H

1


A




B




2





I





II













7



15


14



14

15

16




16

13



10

8


I



II





A - ≥440 mm




B - ≥830 mm

A - ≥94 mm

B - ≥79 mm







13







12

10




11





14

12



II



IV

