





HIETAKARI®




8/25 0SRLM


509/511




# Parts




1. x2




2. 6x30 mm




3. 4.5x44 mm




4. x1



5. x1



6. x1




7. x1




8. x1

# Tools




A




Ø6 mm  
B




C – Silicone




D




E






F





1







2



3





4






5



E

7

8



7

8